

SHIPPING INSTRUCTIONS

FOR LOANER AND REPAIR INSTRUMENTS

1. Screw the four adjustable legs all the way into the base of the reprocessor to be returned.
2. DO NOT ship any accessories (hoses, power cords, etc.).
3. **DO NOT put the reprocessor in the bag.**
4. Package the reprocessor to be returned to Medivators in the box in which your loaner or repaired reprocessor was received.
5. Please return all reprocessors (loaners, as well as those requiring repair) to:

Medivators Reprocessing Systems
a Minntech Corporation Business Group
14605 28th Avenue North
Minneapolis, MN 55447 USA

6. If you have any questions please call Medivators Customer Support at 1-800-444-4729.